

After applying Windows Update 1709, the Soft Keyboard is reduced in size


ISSUE:

After applying Microsoft's Fall Creator Update 1709 or later on your Agile X or Agile X IS tablet PC running Windows 10 IoT, you notice that the virtual keyboard on device has been significantly reduced the size.

This is an issue directly related to Microsoft's release of the Creator Update 1709 for Windows 10. As to date, there is no resolution for this issue from Microsoft.

As solution, we can offer the following script file.

<http://automation.bartec.de/DataRoot/transfer/AgileX/Misc/AdjustKBSize.zip>

1. Unzip the file
2. Copy the file to the device
3. Click with right mouse key on  AdjustKBSize.cmd
4. Run as Administrator
5. After installation restart device

